

No.	Regist	Name	Built	Year O	Year O	Scrapp	Other
	BEG 923	Volvo B10MA-55 / Saffle 2000	1996	1996	1996		Układ drzwi 1-1-1-0
<b>P K 6 9 7 0 G</b>	<b>C C A 0 0 2 2 4</b>	Anyuan PK6970GCC	1997	1997	2005	2005	
	□ A3473 □	Shanghai SK6942LA3	1997	1997			
<b>S 2 A 0 1 6</b>	□ AD6590	Sunwin SWB6120KHV-3	2001	2001	2008	2011	
<b>S 2 B 0 2 4 D</b>	□ AD9648	Volvo B7R Sunwin SWB6120KHV-3	2001	2001			
<b>K G P - 2 9 6</b>	□ AK5870	Sunwin SWB5105KGP-3	2003	2003	2012	2012	
<b>K G P - 3 1 2</b>	□ AK8075	Sunwin SWB5105KGP-3	2003	2003	2012	2012	
<b>K G P - 3 0 2</b>	□ AK5847	Sunwin SWB5105KGP-3	2003	2003	2012	2012	
<b>K G P - 3 1 4</b>	□ AK8125	Sunwin SWB5105KGP-3	2003	2003	2012	2012	
<b>K G P - 3 6 8</b>	□ AK8065	Sunwin SWB5105KGP-3	2003	2003	2012	2012	
<b>K G P - 2 7 6</b>	□ AK5781	Sunwin SWB5105KGP-3	2003	2003	2012	2012	
<b>S 2 C 1 9 9</b>	□ AP8275	Volvo B7R / Sunwinbus SWB6120KH	2004	2007			
<b>S 2 C 2 2 4</b>	□ AP8316	Volvo B7R / Sunwinbus SWB6120KH	2004	2007			
<b>S 2 C 0 8 4</b>	□ AK0978	Volvo B7R / Sunwinbus SWB6120KH	2004	2004			
	□ AQ4000	Sunwin SWB5105KGP-3	2004	2004	2013	2013	
	□ AQ4003	Sunwin SWB5105KGP-3	2004	2004	2013	2013	
	□ AQ3790	Sunwin SWB5105KGP-3	2004	2004	2013	2013	
	□ AQ3976	Sunwin SWB5105KGP-3	2004	2004	2013	2013	
	□ AQ3805	Sunwin SWB5105KGP-3	2004	2004	2013	2013	
<b>S 2 C - 0 6 4</b>	□ AQ8101	Volvo B7R / Sunwin SWB6120KHV2	2004	2004			
	□ AQ9751	Sunwin SWB5105KGP-3	2004	2004	2013	2013	
	□ AQ4030	Sunwin SWB5105KGP-3	2004	2004	2013	2013	
<b>K G P - 3 1 5</b>	□ AK8065	Sunwin SWB5105KGP-3	2004	2004	2012	2012	
<b>S 2 D 0 3 0 G</b>	□ B05827	Sunwin SWB6125	2004	2006	2012	2012	
<b>S 2 D 0 1 4 G</b>	□ AP2542	Sunwin SWB6125	2004	2004	2012	2012	
<b>S 2 C - 6 9 9</b>	□ AK4898	SunwinBus SWB6120KHV2-3	2004	2004			
<b>K G P - 3 5 0</b>	□ AQ4062	Sunwin SWB5105KGP-3	2004	2004	2013	2013	
<b>K G P - 2 8 4</b>	□ AK5805	Sunwin SWB5105KGP-3	2004	2004	2012	2012	
<b>K G P - 3 4 9</b>	□ AQ4069	Sunwin SWB5105KGP-3	2004	2004	2013	2013	
<b>K G P - 3 7 1</b>	□ AQ4059	Sunwin SWB5105KGP-3	2004	2004	2013	2013	
<b>K G P - 3 6 9</b>	□ AQ0430	Sunwin SWB5105KGP-3	2004	2004	2013	2013	
<b>G 0 A - 2 5 0</b>	□ AS2610	Guilin Daewoo GDW6105G	2005	2005			
	□ B16093	King Long XMQ6118Y	2006	2006			XMQ6118Y1
<b>H 0 A 0 3 3 I</b>	□ B08519	Changjiang HZWG100K	2006	2006			
<b>K - 5</b>	□ B06365	Setra S315 HD / Ankai HFF6120K46	2006	2006			
<b>H 0 A - 0 0 2</b>	□ AR5498	Changjiang HZWG100K	2006	2006			
<b>K L Q 1 0 2</b>	□ B39962	Higer KLQ6118GE3	2006	2009			
<b>S 0 E - 2 3 7</b>	□ B51273	Sunwin SWB6100V5	2007	2007	2008		
<b>L V - 4 0 6</b>	□ B 51723	Sunwin SWB6100V5	2007	2007			
	□ Gui lin Daewoo GDW6105G	2007	2007				
<b>S 2 G 1 0 2 C</b>	□ B32588	Sunwin SWB6120V4LE	2007	2009			
<b>Y T K 0 0 0 1</b>	□ B60565	Yutong ZK6926HGA	2008	2009			
<b>Q 4 A 0 0 6</b>	□ B61166	Youngman JNP6180G	2008	2008	2009		
<b>Q 4 A 0 0 3</b>	□ AF0305	Youngman JNP6180G	2008	2008	2009		
<b>W 8 A 0 5 1 H</b>	□ B52243	Wonsun SXC6890G	2008	2011			
	□ B21538	Daewoo BS120 / Wonsun SXC6120G	2008	2008			
	□ B46975	Daewoo BS120 / Wonsun SXC6120G	2008	2008			
<b>W 2 B 0 1 8</b>	□ B47425	Daewoo BS120 / Wonsun SXC6120G	2008	2008	2009		
<b>S 2 F - 0 5 3 A</b>	□ B51349	Sunwin SWB6120V4LE	2008	2008			
<b>Q 4 A 0 0 8</b>	□ B61170	Youngman JNP6180G	2008	2008	2009		
<b>S 2 G 2 1 2 C</b>	□ B89143	Sunwin SWB6120V4LE	2009	2009			
<b>S 2 G 1 6 1 C</b>	□ B84837	Sunwin SWB6120V4LE	2009	2009			
<b>S 2 G 1 7 9 C</b>	□ B84740	Sunwin SWB6120V4LE	2009	2009			
<b>0 2 3 1</b>	□ B67933	Sunwin SWB6890MG	2009	2009			
<b>S 2 G 1 1 7 C</b>	□ B89141	Sunwin SWB6120V4LE	2009	2009			
<b>S 8 B 3 4 1 C</b>	□ B79842	Sunwin SWB6890MG	2009	2009			
<b>W 0 B 0 2 0 I</b>	□ B72245	Daewoo BS106 Wonsun SXC6105G	2009	2009			
<b>S 2 L 0 1 3 C</b>	□ BD5142	Sunwin SWB6127HE2	2010	2010			
<b>S 2 K - 0 1 5 G</b>	□ BE1427	Sunwin SWB6121SC	2010	2010			
<b>S 2 K - 0 1 2 G</b>	□ BE2640	Sunwin SWB6121SC	2010	2010			
<b>S 2 I 0 2 5 I</b>	□ BD3746	Sunwin SWB6121EV	2010	2010			
<b>S 2 K 0 5 3 G</b>	□ BD2441	Sunwin SWB6121SC	2010	2010			
<b>S 2 K - 0 4 5 G</b>	□ BD3427	Sunwin SWB6121SC	2010	2010			
<b>S 2 K 0 0 5 G</b>	□ BE2549	Sunwin SWB6121SC	2010	2010			

<b>W 2 E 0 1 4</b>	<input type="checkbox"/> BD6418	Daewoo BS120 Wonsun SXC6120G	2010	2010			
<b>S 2 L 0 1 4 E</b>	<input type="checkbox"/> BD8486	Sunwin SWB6127HE2	2010	2010			
<b>Y 2 A - 0 0 1</b>	<input type="checkbox"/> B E9457	Changlong YS6120DG	2010	2010			
<b>J 2 B - 0 0 0 1</b>		Youngman JNP6120BEV1	2013	2014			
<b>S 2 P - 0 0 2 3</b>	<input type="checkbox"/> D64235	SWB6128V8LF	2013	2013			
<b>S 2 P - 0 6 1 9</b>	<input type="checkbox"/> D85940	Sunwin SWB6128V8LF	2014	2014			
<b>J 2 B - 0 0 8 0</b>	<input type="checkbox"/> D96400	Youngman JNP6120BEV1	2014	2014			
<b>S 2 S - 0 0 9 8</b>	<input type="checkbox"/> D 97681	Sunwin SWB6127HE2	2014				
<b>S 2 S - 0 0 3 4</b>	<input type="checkbox"/> D96117	Sunwin – / Sunwin Hybrid SWB6127P	2014	2014			
<b>J 2 B - 0 2 3 9</b>	<input type="checkbox"/> DC7351	Youngman JNP6120BEV1	2014	2014			
<b>W 1 C - 0 2 6 3</b>	<input type="checkbox"/> D P0596	SXC6890G	2016				Wanxiang SXC6110GBEV3
<b>Z 2 E - 0 2 3 1</b>	<input type="checkbox"/> DP9685	Yutong ZK6125BEVG12	2016	2016			
<b>Z 2 F - 0 0 6 8</b>	<input type="checkbox"/> DR1701	Yutong Metrobus ZK5120C	2017	2017			
	<input type="checkbox"/> DR1137	Yutong Metrobus ZK5180A	2017	2017			Yutong ZK5180A
<b>Z 5 A - 0 0 2 9</b>	<input type="checkbox"/> DR7537	Yutong Metrobus ZK5180A	2017	2017			
<b>S 0 R - 0 0 3 6</b>	<input type="checkbox"/> A55827D	Sunwin Electric SWB6109BEV36	2019	2019			
<b>S 2 Y - 0 3 7 8</b>	<input type="checkbox"/> A53168D	Sunwin SWB6129BEV	2019	2019			
<b>H 0 A - 0 0 7</b>	<input type="checkbox"/> A T8355	Changjiang HZWG100K					
<b>Z 2 F - 0 0 7 2</b>	<input type="checkbox"/> D S2571	Yutong Metrobus ZK5120C					Yutong ZK5120C
<b>Z 5 A - 0 0 0 5</b>	<input type="checkbox"/> D R2192	Yutong Metrobus ZK5180A					
<b>Z 5 A - 0 0 1 0</b>	<input type="checkbox"/> D R1530	Yutong Metrobus ZK5180A					Yutong ZK5180A
		Changjiang HZWG100K					
	<input type="checkbox"/> B67331	Sunwin SWB6106HG		2008			
	<input type="checkbox"/> A S0841	Guilin Daewoo GDW6105G					
<b>S 2 A - 4 9 4</b>	<input type="checkbox"/> A H6218	Volvo B7R Sunwin SWB6120KHV-3					
<b>S 0 D - 0 1 8</b>	<input type="checkbox"/> A T3976	Sunwin SWB6120KHV-3					
<b>S 2 G - 2 1 3 C</b>	<input type="checkbox"/> B 89679	Sunwin SWB6120V4LE					
<b>S 0 D - 1 5 2</b>	<input type="checkbox"/> B02527	Sunwin SWB6120KHV-3					
<b>S 2 A - 0 7 1</b>	<input type="checkbox"/> A H5395	Volvo B7R Sunwin SWB6120KHV-3					
<b>H 0 A - 0 2 9</b>	<input type="checkbox"/> B 08505	Changjiang HZWG100K					
	<input type="checkbox"/> B81447	Sunwin SWB6106		2008			
	<input type="checkbox"/> B 81647	Sunwin SWB6106		2008			
<b>S 2 P - 0 6 3 4</b>	<input type="checkbox"/> D 85979	Sunwin SWB6128V8LF					
<b>H 0 A - 0 0 2</b>	<input type="checkbox"/> A R5498	Changjiang HZWG100K					
<b>J 2 B - 0 2 2 3</b>	<input type="checkbox"/> D C7248	Youngman JNP6120BEV1					
<b>S 2 P - 0 5 0 8</b>	<input type="checkbox"/> D 88736	Sunwin SWB6128V8LF					
<b>J 2 B - 0 2 7 0</b>	<input type="checkbox"/> D D9881	Youngman JNP6120BEV1					