

No.	Regist	Name	Built	Year O	Year O	Scrapp	Other
	AW 73 787	DAB LOPSUC 1/11	1967	1972	1973		
2 0	ML 94 761	DAB LK575-690/3	1976	1986	1992		
2 3	DH 97 631	DAB LIDRT 6857/3	1976	1984	1989		
2 2	DH 97 682	DAB LIDRT 6857/3	1976	1984	1989		
	EJ 88 234	Volvo B58-60 / Aabenraa M75	1977	1977	1979		
	EJ 88 234	Volvo B58-60 / Aabenraa M75	1977	1977	1979		
1 9	GKA T424	DAB LK575-690/3	1980	1983	1992	2007	
1 6	NK 92 372	DAB 6-5-690/3	1981	1981	1993		
1 0	NK 92 347	DAB 6-5-690/3	1981	1981	1993		
1 4	HV 97 444	DAB 6-5-TL11/3	1982	1984	1995		
1 2	NB 89 209	DAB 6-5-TL11/3	1982	1983	1995	1998	
1 1	LC 05852	DAB 7-1200 L	1984	1984	1995	2021	14.09.1984 r.
5	JP 94 485	DAB 7-1200 L	1984	1984	1992	2007	31.12.2007 Demontaż na wniosek
1 0	UE 96 645	DAB 7-1200 L	1984	1984	1995		
1 3	LC 05851	DAB 7-1200 L	1984	1984	1995	2021	14.09.1984
2 6	SK 8858A	DAB 7-1200 L	1985	1987	1995		
2 5	TZ 94 165	DAB 7-1200 L	1986	1989	1992	2013	
2 1	XM 96 071	DAB 7-1200 L	1987	1987	1992		
2 9	LZ 18893	DAB 7-1200 L	1988	1989	1992	2010	21.09.1988
2 7	LJ 97 075	DAB 7-1200 L	1988	1988	1992	2012	
2 8	LRV CK18	DAB 7-1200 L	1988	1988	1992		08.02.1988 ☐ ☐ Zbycie pojazdu: 27.07.2021 ☐ ☐ Autobus należał do
2 3	FZ 80098	DAB 7-1024L	1989	1989	1995	2023	(03.04.1989) Data produkcji / Data pierwszej rejestracji. ☐ ☐ 1989
	665 MET	Scania K113TLB / Carrus Superstar	1990	1990	1999		
2 2	XK 92 142	DAB 12-1200L	1992	1992	1995		
2 1	UB 95 315	DAB 12-1200L	1992	1992	1995		