

No.	Regist	Name	Built	Year O	Year O	Scrapp	Other
	BKA 11-34	Karosa LC735.00	1984	?	2011		
	BKA 54-02	Karosa LC736.1022	1992	2000	2011		
	3SM 4182	Karosa C934.1351	1998	2011	2015		___.07.1998□ □ ___.11.2004 DPÚK□ □ ___.01.2007 Most□ □ ___.05.2007 Most□ □ ___.05.2011 Dopaz□ □ ___.06.2015 CARIN
	4B2 0021	Karosa C934.1351	1998	2007	2014		
	ZS 316AM	SOR C9,5	1999	2007	2013		03.05.1999□ □ □ □ Ostatnie badanie techniczne ważne do 13.05.2007
	7B0 8902	Karosa C934.1351	1999	2011			___.05.2007 Most□ □ ___.05.2011 Dopaz□ □ ___.06.2015 CARIN
	7B0 8903	Karosa C934.1351	1999	2011	2016		___.05.2007 Most□ □ ___.05.2011 Dopaz□ □ ___.01.2016 Výrava
	8C0 0074	Renault Iliade RTX	1999	2003	2018		
	KTA 36077	SOR C10,5	2000	2007	2013	2019	Data pierwszej rejestracji: 22/11/2000
	ZS 317AM	SOR C10,5	2000	2007	2013		
	7B0 8904	Karosa C934E.1351	2000	2011	2015		___.11.2000□ □ ___.05.2007 Most□ □ ___.05.2011 Dopaz□ □ ___.06.2015 CARIN
	WSK TC93	SOR C10,5	2000	2007	2012	2021	Pierwsza rejestracja: 26.09.2000
	BKE 93-03	Karosa C955.1073	2001	2001			
	1BB 4126	Karosa C954.1360	2002	2015			
	2B7 0909	Karosa LC956.1072	2002	2005			
	4K6 8925	Karosa LC956.1072	2002	2004	2019		
	4B9 9405	Volvo 9700H 12,2m	2006	2008			
	4B9 9404	Volvo 9700H NG	2008	2008			B12B 4x2□ □ 12,3m
	1BY 3655	Irisbus Crossway 12 LE	2010	2018			
	1BY 3665	Irisbus Crossway 12 LE	2010	2018			
	1BY 3668	Irisbus Crossway 12 LE	2010	2018			
	1BY 3667	Irisbus Crossway 12 LE	2010	2018			
	1BY 3664	Irisbus Crossway 12 LE	2010	2018			
	7B0 7271	Volvo 9700H NG	2010	2010			
	8B8 7517	SOR C12	2012	2012			
	4E5 8154	SOR CN12	2012	2012			
	1BF 1120	Scania TK EB4x2NI Touring HD	2016	2016			
	5B0 2199	SOR C10,5					